



REV	ECO#	BY	DATE	CHK	DESCRIPTION
A	14921	DB	1.14.05	FDJ	RELEASE
B	17936	BH	2.21.06	FDJ	UPDATE MID LEVEL SENSOR CONNECTOR
C	18560	BH	8.18.06	FDJ	ERROR CORRECTION, DBJ4 PIN 3
D	20352	DB	4.12.07	DBJ	CLARIFY CONNECTIONS TO PWR SWITCH. CORRECT ERROR ON DBJ5/LLP5.



**CONTROLLED**

This document is the property of Fresenius Medical Care North America, Inc. (Fresenius) and contains confidential and trade secret information of Fresenius. This document may only be transferred from the custody or control of Fresenius only as authorized by Fresenius and then only by way of loan for limited purposes. It must not be reproduced in whole or in part and must be returned to Fresenius upon request and in all events upon completion of the purpose of the loan. Neither this document nor the information it contains may be used or disclosed to persons not having a need for such use or disclosure consistent with the purpose of the loan, without prior written consent of Fresenius.

APPROVALS:	DATE:	Tolerances Unless Specified:	Title
DRAWN: D.BRIDGEDALE	3.15.07	.XXX +0.005", XX +0.01" Dia. ±0.003", X° ±0.5° Fractions +1/32"	<b>Granuflo II Wiring Diagram</b>
APPR: <i>D. Bridgedale</i>		Fresenius Medical Care North America 2637 Shadlands Drive Walnut Creek, CA 94598 925 - 295 - 0200	Size: <b>B</b> Number: <b>260063</b> Revision: <b>D</b>
CHECK:		Date: 15-Mar-2007 Time: 14:22:56	Sheet 1 of 1
File: C:\Documents and Settings\dbridgedale\My Documents\DWG 260063 GRANUFLO II WIRING DIAGRAM.dwg - Documents\260063.S			